

Phone: (714) 736-4800 | Fax: (714) 736-4840

SUPPLIER QUALITY ASSURANCE REQUIREMENTS

MATERIAL SUPPLIERS: QA1, QA2, QA3, QA4, QA5, QA6, QA7, QA8, QA9, QA10, QA11, QA12, QA13, QA14, QA15, QA16, QA17, QA18, QA19, QA20, QA21, QA23, QA24, QA25, QA26 (AS APPLICABLE)

PROCESSING SUPPLIERS: QA1, QA2, QA3, QA4, QA5, QA6, QA7, QA8, QA9, QA10, QA12, QA13, QA14, QA15, QA16, QA18, QA19, QA20, QA21, QA22, QA23, QA24, QA25, QA26 (AS APPLICABLE)

MRO OR PACKING SUPPLIERS: QA2, QA6,QA7, QA8, QA9, QA11, QA12, QA14, QA16, QA19, QA20, QA21 (AS APPLICABLE)

QA1	Clear, legible, unaltered Material Test Reports or authorized release certificates are required with all
	material shipments.
QA2	Suppliers shall furnish material that complies with all purchase order requirements documented on the
	Purchase Order.
QA3	All material processing records, testing records, and test reports must be retained for a minimum of 10
	years and dispositioned per supplier's procedures.
QA4	Supplier shall maintain a quality system that has been approved by Bralco Metals.
QA5	Bralco Metals shall have the right to inspect and/or test all material, at its source or destination, prior to
	acceptance.
QA6	Bralco Metals reserves the right to return, at the supplier's expense, any material found to be defective or
	out of compliance with applicable specifications.
QA7	Material must be packaged to protect from physical damage and exposure to water in transit or it may be
	subject to rejection by Bralco Metals.
QA8	Suppliers are required to flow down to sub-tiers any applicable requirements.
QA9	Supplier shall comply with all local, state, and federal laws and/or regulations in the performance of a
	purchase order.
QA10	All drawings, blueprints, patterns, and/or samples paid for by Bralco Metals or supplied by Bralco Metals
	shall not be used by the supplier except in the execution of a Bralco Metals purchase order.
QA 11	Safety Data Sheets (SDS) for material purchased shall be made available upon request.
QA12	Bralco Metals reserves the right to require its suppliers grant, us, our customer, our customer's customer
	and regulatory agencies, the right of access to the supplier's premises for the purpose of verifying the
	quality of work, all applicable records, and/or materials at any level of the supply chain involved in the
	fulfillment of the purchase order.
QA13	Suppliers are required to maintain a measuring and test equipment calibration system. This system must
	have certifications that are traceable to N.I.S.T. and certifications must be maintained for a minimum of 10
	years.
QA14	Suppliers are required to provide Bralco Metals notification for nonconforming product or change of
	location of manufacturer and obtain approval prior to shipment.

Doc Name: R-843 Supplier Quality Assurance Requirements

Rev: C

Effective Date: 4/21/20

Approved By: Quality Manager



rs, change in ain approval must be be separated a minimum it is correct, oduct or tion, repair,
must be be separated a minimum it is correct, oduct or
it is correct,
it is correct,
a minimum it is correct,
it is correct,
it is correct,
oduct or
oduct or
ion, repair,
y, and the
te exhibiting
ed materials.
ce accurately
ces (e.g.

Doc Name: R-843 Supplier Quality Assurance Requirements

Rev: C

Effective Date: 4/21/20

Approved By: Quality Manager